





GRAPHIC TIES
(SKETCHED)

SEC 31 TWP 23 RANGE 6

6-29-81




CORNER IDENT. STONE FNP

TIES: 1. 53.36' DWP
2. 35.76' SIGN POST
3. 45.90' TEL: PED.
4. 32.06' HP
5. 65.56' PWP
6. 26.82' PWP
7. 26.23' PWP


SEC 31 TWP 23 RANGE 6

DATE: 7/2/01

SECTION 31 TWP. 22 RANGE 6



GRAPHIC TIES (SKETCHED)



REFERENCED BY:

L. CLINE
D. TRAGESSER

CORNER IDENTIFIED: STONE FOUND AT SURFACE


TIES:

1. 21.65' IRON ROD SET AT EDGE OF ROAD


2. 7.95' IRON ROD SET AT EDGE OF ROAD

SECTION 31 TWP. 22 RANGE 6

SEC. 31 TWP 23 RANGE 6



GRAPHIC TIES
(SKETCHED)




CORNER IDENT. IRON ROD FOUND

- TIES: 1. 75.68 - BOLT AT SOUTHWEST CORNER OF CONCRETE PAD.
2. 92.23 - WEST-SOUTHWEST BOLT ON WELL CAP.
3. 5.64 - IRON ROD SET AT SOUTH EDGE OF ROAD


SEC 31 TWP 23 RANGE 6

9/99

SEC. 31 TWP 23 RANGE 6



GRAPHIC TIES
(SKETCHED)




CORNER IDENT. IRON ROD


TIES: 1. 26.55 PK NAIL IN HEADPOST
2. 25.65 " " " TELEPHONE POLE
3. 60.7 " " " POWER POLE
4. 60.75 " " " HEADPOST

SEC. 31 TWP 23 RANGE 6

SEC 31 TWP 23 RANGE 6



GRAPHIC TIES
(SKETCHED)




CORNER IDENT. NOT STATED

TIME: 1. 26.55' HP

2. 33.41' 22' HICKORY TREE


3. 26.45' PWP

SEC 31 TWP 23 RANGE 6



GRAPHIC TIES
(SKETCHED)

SEC 31 TWP 23 RANGE 6




CORNER IDENT. NOT STATED


TIES:	1.	19.30'	HP
	2.	20.30'	PWP
	3.	42.40'	PWP
	4.	28.70'	HP

SEC 31 TWP 23 RANGE 6

SEC. 31 TWP 23 RANGE 6



GRAPHIC TIES
(SKETCHED)



CORNER IDENT. STONE FOUND FLUSH

- TIES: 1. 13.54 - P.K. NAIL IN EAST FACE HEAD POST
2. 20.00 - P.K. NAIL IN EAST FACE FENCE POST
3. 9.89' - IRON ROD SET ON SOUTH EDGE ROAD



SEC 31 TWP 23 RANGE 6

9/99

REFERENCE SHEET

SECTION 32 TOWNSHIP 23 RANGE 6 EAST

DATE OF RECOVERY MAY 24, 2002



INDIANA COORDINATE VALUES (NAD83)

OBSERVATION DATE: -

CREW: -

NORTH: - EAST: -

ELEVATION: -

LATITUDE: -

LONGITUDE: -

DRAWN BY: R.K.

CREW: ROD KELLY, JARED HENRY

JOB # 02-075 MANVILLE


TYPE OF MARKER IDENTIFIED: STONE FOUND 0.45' BELOW SURFACE OF CHIP AND SEALED ROAD

HISTORY AND DESCRIPTION OF RECOVERED POINT:


I FOUND NO CURRENT REFERENCES IN THE COUNTY SURVEYOR'S OFFICE PERTAINING TO THIS QUARTER SECTION MONUMENT.
THIS STONE WAS FOUND BY US ON 05/24/2002.

REFERENCE	DISTANCE	-DESCRIPTION-	FOUND SET	
1.	15.56'	PK NAIL WITH IDENTIFYING WASHER IN POST	☐	☒
2.	67.98'	PK NAIL WITH IDENTIFYING WASHER IN POWERPOLE	☐	☒
3.	18.05'	IRON PIPE 0.80' BELOW GRADE	☒	☐
4.	21.66'	IRON ROD WITH IDENTIFYING CAP AT EDGE OF ROAD AT GRADE	☐	☒
-	-	-	☐	☐
-	-	-	☐	☐
-	-	-	☐	☐
-	-	-	☐	☐

SEC. 32 TWP 23 RANGE 6



GRAPHIC TIES
(SKETCHED)




CORNER IDENT. R.L.S. FOUND

TIES: 1. 22.95 - P.K. NAIL IN EAST FACE POWER POLE.
2. 36.53 - EAST FACE OF YELLOW PIPE LINE MARKER


SEC 32 TWP 23 RANGE 6

9/99

SEC. 32 TWP 23 RANGE 6



GRAPHIC TIES
(SKETCHED)



CORNER IDENT. "A" = IRON PIPE FOUND - "B" = STONE FOUND 1' DEEP

TIES:

"A"

1. 34.52 - P.K. NAIL IN POWER POLE

2. 17.75 - P.K. NAIL IN HEAD POST

"B"

1. 36.49 - P.K. NAIL IN POWER POLE


2. 19.30 - P.K. NAIL IN HEAD POST

SEC 32 TWP 23 RANGE 6


9/99

DATE: 7/3/01

SECTION 32 TWP. 23 RANGE 6



GRAPHIC TIES (SKETCHED)



REFERENCED BY:

L. CLINE
D. TRAGESSER


CORNER IDENTIFIED: STONE FOUND, LOWERED 3', SET IRON ROD.

TIES:


-
1. 25.55 P.K. NAIL IN EAST FACE P.W.P.
-
2. 60.00 P.K. NAIL IN SOUTH FACE P.W.P.
-
3. 47.63 P.K. NAIL IN WEST FACE TELEPHONE POLE
-
-
-
-
-

SECTION 32 TWP. 23 RANGE 6

SEC. 32 TWP 23 RANGE 6



GRAPHIC TIES
(SKETCHED)



CORNER IDENT. STONE w/ "X" FOUND 1' DEEP w/ R.R.S. ON TOP


- TIES: 1. 25.55 - P.K. NAIL IN EAST FACE POWER POLE.
2. 60.00 - P.K. NAIL IN SOUTH FACE POWER POLE.
3. 47.43 - P.K. NAIL IN WEST FACE TELEPHONE POLE

SEC 32 TWP 23 RANGE 6


9/99

DATE: 7/2/01

SECTION 32 TWP. 22 RANGE 6



GRAPHIC TIES (SKETCHED)



REFERENCED BY:

L. CLINE
D. TRAGESSER

CORNER IDENTIFIED: STONE FOUND AT SURFACE


TIES:

1. 21.65' IRON ROD SET AT EDGE OF ROAD


2. 7.95' IRON ROD SET AT EDGE OF ROAD

SECTION 32 TWP. 22 RANGE 6

SEC. 32 TWP. 23 RANGE 6



GRAPHIC TIES
(SKETCHED)




CORNER IDENT. IRON ROD FOUND

- TIES: 1. 75.68 - BOLT AT SOUTHWEST CORNER OF CONCRETE PAD.
2. 92.23 - WEST-SOUTHWEST BOLT ON WELL CAP.
3. 5.64 - IRON ROD SET AT SOUTH EDGE OF ROAD


SEC. 32 TWP. 23 RANGE 6

9/99

SEC. 32 TWP. 23 RANGE 6



GRAPHIC TIES
(SKETCHED)




CORNER IDENT. STONE FOUND FLUSH

TIES: 1. 19.66 - P.K. NAIL IN NORTHEAST CORNER HEAD POST
2. 18.69 - E TOP OF CMP.


SEC 32 TWP 23 RANGE 6

9/99

SEC. 33 TWP. 23 RANGE 6



GRAPHIC TIES
(SKETCHED)



CORNER IDENT. R.L.S. Found

TIES: 1. 22.95 - P.K. NAIL IN EAST FACE POWER POLE.
2. 36.53 - EAST FACE OF YELLOW PIPE LINE MARKER

SEC. 33 TWP. 23 RANGE 6

9/99